FVUI V0.11.6 (202411022003) Version release log

1. Declaration

FLYÍNGVOICE

The latest firmware cannot directly downgrade two major versions. For example, if you need to downgrade the V0.8. X firmware, you need to first downgrade to the V0.9. X firmware.

2.Introduction

- Firmware version:FVUI_7628_V0.11.6_202411022003_RC.bin
- Version upgrade: Upgrade from V0.10.46 (202408231702) to V0.11.6 (202411022003)
- Applicable models: P10/P10P/P10G/P10LTE/P11/P11P/P11G/P11LTE
- Release date: 2024.11.08

3.New Features

- 1. Add sip server2, sip server3.
- 2. Add xml browser processing post requests, beep ring parameter support, and phone status functions.
- 3. Add the timing task function.
- 4. Add the Idaps and Idap TLS start functions.

4.Function optimization

- 1. Modify the ldaps processing logic to modify the original certificate path in the environment variable to use the configuration file.
- 2. Modify the network loop detection logic from script detection to C language detection, including wired and wireless.
- 3. IPV 4 is default when sim IP type is not specified.
- 4. For option probe, call-id was randomly generated and cseq fixed to 1.
- 5. Idap phone book add Idaps support and its certificate upload interface.

5.Problem fixing

- 1. Repair the wrong connection message when the enterprise address book queries contacts.
- 2. Repair the call cannot be cancelled after receiving cancel at 200OK.
- 3. Repair the problem that differential ringing is not effective.

0

深圳总部:广东省深圳市南山区桃源街道留仙大道南山智园崇文园区1号楼1801-1802 / 1801-1802, Building 1, Chongwen Park, Nanshan Zhiyuan, Nanshan District, Shenzhen, China 北京分公司:北京市石景山区金安中海财富中心A座401 / Rm 401, Building 1, JinAn Zhonghai Fortune Center, Shijingshan District, Beijing, China

FLYINGVOICE

- 4. Fix an error in configuring apn when the IP protocol type is not specified.
- 5. Repair customer l2tp environment sip message does not walk l2tp cause call silent problem.
- 6. Fix a crash issue when tr069 gets the Device.IP.InterfaceNumberOfEntries.
- 7. Fix problems that the Brazilian velans EC800E module Ite phone cannot get the network.

深圳总部:广东省深圳市南山区桃源街道留仙大道南山智园崇文园区1号楼1801-1802 / 1801-1802, Building 1, Chongwen Park, Nanshan Zhiyuan, Nanshan District, Shenzhen, China 北京分公司:北京市石景山区金安中海财富中心A座401 / Rm 401, Building 1, JinAn Zhonghai Fortune Center, Shijingshan District, Beijing, China 上海分公司:上海市杨浦区隆昌路619号城市概念软件园1幢C108 / Rm C108, City Concept Building 1, Longchang Rd No. 619, Yangpu District, Shanghai, China