







FVUIADV V0.11.6 (202411021815) Version release log

1. Declaration

The latest firmware cannot directly downgrade two major versions. For example, if you need to downgrade the V0.8. X firmware, you need to first downgrade to the V0.9. X firmware.

2.Introduction

- Firmware version: FVUIADV_7628_V0.10.52_202409021714_RC.bin
- Version upgrade: Upgrade from FVUIADV V0.10.52 (202409021714) to FVUIADV V0.11.6 (202411021815)
- Applicable models: P20,P20P, P20G, P21, P21P, P22P, P22G, P23G, P23GW, P10W, P11W, FIP12WP, FIP12WP-R
- Release date: 2024.11.08

3.New Features

- 1. Add xml browser processing post requests, beep ring parameter support, and phone status functions.
- 2. Add the timing task function.
- 3. Add the Idaps and Idap TLS start functions.

4. Function optimization

- 1. Idap phone book add Idaps support and its certificate upload interface.
- 2. Modify the Idap certificate store directory and the certificate generation location.
- 3. Modify the network loop detection logic from script detection to C language detection, including wired and wireless.
- 4. Change the flip light flash type to a quick flash.
- 5. Reduce the volume of signaling sounds by 6 db because there will be noise when the volume is high.
- 6. Remove the reset logic during the soft restart.

5. Problem fixing

- 1. Fix a crash issue when tr069 gets the Device.IP.InterfaceNumberOfEntries.
- 2. Repair the problem that the second dial does not take effect when the phone uses the inband.
- 3. Repair the problem that differential ringing is not effective.
- 4. Repair the call cannot be cancelled after receiving cancel at 200OK.









5. Repair the wrong connection message when the enterprise address book queries contacts.

FLYINGVOICE

